

# Energy performance certificate (EPC)

22 HIGH STREET  
CANNINGTON  
BRIDGWATER  
TA5 2HE

Energy rating

D

Valid until 29 March 2031

Certificate number

4839-7127-5000-0930-5272

## Property type

Detached house

## Total floor area

129 square metres

## Rules on letting this property


Properties can be rented if they have an energy rating from A to E.

If the property is rated F or G, it cannot be let, unless an exemption has been registered. You can read [guidance for landlords on the regulations and exemptions \(https://www.gov.uk/guidance/domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance\)](https://www.gov.uk/guidance/domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance).

## Energy efficiency rating for this property

This property's current energy rating is D. It has the potential to be C.

[See how to improve this property's energy performance.](#)



The graph shows this property's current and potential energy efficiency.

Properties are given a rating from A (most efficient) to G (least efficient).

Properties are also given a score. The higher the number the lower your fuel bills are likely to be.

The average energy rating and score for a property in England and Wales are D (60).

### Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- very good (most efficient)
- good
- average
- poor
- very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

| Feature              | Description                                    | Rating  |
|----------------------|------------------------------------------------|---------|
| Wall                 | Cavity wall, as built, no insulation (assumed) | Poor    |
| Roof                 | Pitched, 100 mm loft insulation                | Average |
| Window               | Fully double glazed                            | Good    |
| Main heating         | Boiler and radiators, mains gas                | Good    |
| Main heating control | Programmer, room thermostat and TRVs           | Good    |